

FILE NOTATIONS

Entered in NID File ✓
 Entered On S R Sheet ✓
 Location Map Pinned ✓
 Card Indexed ✓
 I W R for State or Fee Land

Checked by Chief RLJ
 Copy NID to Field Office ✓
 Approval Letter ✓
 Disapproval Letter

COMPLETION DATA:

Date Well Completed 3-14-61 Location Inspected 4-2-62
 OW..... WW..... TA..... Bond released
 GW..... OS..... PA ✓ State of Fee Land

LOGS FILED

Driller's Log 3-24-61
 Electric Logs (No.) 2
 E ✓ E-I GR GR-N Micro
 Lat Mi-L Sonic ✓ Others

EFFECTIVE NOVEMBER 1, 1964, CHAMPLIN
 OIL & REFINING COMPANY MERGED WITH
 CELANESE CORPORATION OF AMERICA.

NEW NAME: CHAMPLIN PETROLEUM COMPANY

Champlin Oil & Refining Co.

P. O. BOX 451
SIDNEY, NEBRASKA

February 16, 1961

Utah Oil & Gas Commission
State Capitol Building
Salt Lake City 14, Utah

re: Navajo-111 No. 3
San Juan County, Utah

Gentlemen:


Attached are seven (7) copies of Form OGCC-1, "Notice of Intention to Drill" the subject named well.

If the proposed work meets with your approval please execute and return five executed copies to this office.

Thank you.


Very truly yours,

CHAMPLIN OIL & REFINING CO.


D. C. Carley
District Supt.

/mew

Atts.



R24E

STATE OF UTAH
OIL & GAS CONSERVATION COMMISSION
 SALT LAKE CITY, UTAH

T4S

Fee and Patented.....☐
 State☐
 Lease No.
 Public Domain☐
 Lease No.
 Indian Navajo Tribal ☒
 Lease No. 11-20-603-720

SUNDRY NOTICES AND REPORTS ON WELLS

Notice of Intention to Drill..... <input checked="" type="checkbox"/> Notice of Intention to Change Plans..... <input type="checkbox"/> Notice of Intention to Redrill or Repair..... <input type="checkbox"/> Notice of Intention to Pull or Alter Casing..... <input type="checkbox"/> Notice of Intention to Abandon Well..... <input type="checkbox"/>	Subsequent Report of Water Shut-off..... Subsequent Report of Altering Casing..... Subsequent Report of Redrilling or Repair..... Supplementary Well History.....
--	--

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

16 February, 19 61

Navajo-111
 Well No. 3 is located 1980 ft. from {N} line and 660 ft. from {E} line of Sec. 13
 G-NE-SE, Section 13 43S 24E Salt Lake City
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
 Unnamed San Juan Utah
(Field) (County or Subdivision) (State or Territory)

Will be furnished when available.

The elevation of the derrick floor above sea level is _____ feet.

A drilling and plugging bond has been filed with U. S. Dept. of Interior, Bureau Indian Affairs,
 Washington 25, D. C.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important work, surface formation, and date anticipate spudding-in.)

1. 8-5/8" O.D., 24 lb/ft surface will be run to approximately 500' and cemented to surface.
2. 7-7/8" hole will be drilled below surface to T. D.
3. If commercial production is obtained, 5 1/2" O.D. 15.50 lb/ft, J-55 casing will be set through all productive zones and cemented. Also a D V tool will be run in the 5 1/2" O.D. casing string at approximately 1100' and sufficient cement will be displaced out the D V tool to raise the cement back to 400'.
4. Estimated depths of objective formations: Ismay A zone 5190-5250 Desert Creek 5400-5480.
5. Approximate spud date 2-23-61.
6. Plat will be forwarded as soon as it is available.

I understand that this plan of work must receive approval in writing by the Commission before operations may be commenced.

Company Champlin Oil & Refining Co.

Address Box 451

Sidney, Nebraska

By

Title

District Supt.

INSTRUCTIONS: A plat or map must be attached to this form showing the location of all leases, property lines, drilling and producing wells, within an area of sufficient size so that the Commission may determine whether the location of the well conforms to applicable rules, regulations and orders.


Company.....CHAMPLIN OIL AND REFINING COMPANY.....

Lease.....Navajo-111.....Well No. 3.....

Sec. 13....., T. 43 S., R. 24 E., S.L.M.

Location.....1980' FROM THE SOUTH LINE AND 660' FROM
THE EAST LINE.....

Elevation.....5099.0 UNGRADED GROUND.....



Scale—4 inches equal 1 mile.

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Seal:

James P. Leese

Registered Land Surveyor.

James P. Leese

Utah Reg. No. 1472

Surveyed17 February....., 19 61.....

SAN JUAN ENGINEERING COMPANY, FARMINGTON, N. M.

WELL ELEVATION SURVEY

Company CHAMPLIN OIL AND REFINING COMPANY


Lease Navajo - Murphy Well No. 3

Sec. 13 T. 43 S. N. R. 24 E, ~~SECTION~~ S.L.N.

Location 1980' from the South line and 660' from the East line.

SAN JUAN COUNTY

UTAH



N

Scale—4 inches equal 1 mile.

Ungraded ground elevation

Graded ground elevation 5104.4

Derrick floor elevation 5113.4

Temporary bench mark elevation

Remarks: KB 5115

SAN JUAN ENGINEERING CO.
Farmington, New Mexico

Date Surveyed 27 February 1961

February 20, 1961

Champlin Oil & Refining Co.
Box 451
Sidney, Nebraska

Attn: D. C. Carley, Dist. Supt.

Gentlemen:

This is to acknowledge receipt of your notice of intention to drill well No. Navajo 111-3, which is to be located 1980 feet from the south line and 660 feet from the east line of Section 13, Township 43 South, Range 24 East, S1E4M, San Juan County, Utah.

Please be advised that insofar as this office is concerned approval to drill said well is hereby granted.

This approval terminates within 90 days if the above mentioned well has not been spudded in within said period.

Very truly yours,

OIL & GAS CONSERVATION COMMISSION

CLEON B. FREIGHT,
EXECUTIVE SECRETARY

CBF:awg

cc: P. T. McGrath, Dist. Eng.
U. S. Geological Survey

H. L. Coonts - OGCC, Moab

(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R359.4.
approval expires 12-31-60.

Indian Agency Navajo

Tribal

Allottee _____

Lease No. 14-20-603-720

13		

T43S

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

R24E

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Surface casing report	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Navajo-111

2/27/1961

Well No. 3 is located 1980 ft. from NT line and 660 ft. from E line of sec. 13
C-NE-SE Section 13 43S 24E Salt Lake City
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Unnamed San Juan Utah
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5113.4 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded well 2/26/61. Drilled 12 1/4" hole to 519'. Set 8 5/8" 24# J-55 casing at 499.97. Cemented casing with 300 sacks cement. Had returns to surface. Wait on cement 24 hrs. Pressure tested casing to 700# with water for 30 min. Commenced drilling surface casing plug 3:15 P.M. 2/27/61.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Champlin Oil & Refining Co.

Address Box 451
Sidney, Nebraska

Original Signed By
D. C. Carley

By _____

Title District Supt.

February 28, 1961

United States Geological Survey
P. O. Box 959
Farmington, New Mexico

Attn: Mr. Phil McGrath

Re: Navajo-111 No. 3
San Juan County, Utah

Gentlemen:

Enclosed herewith is an original and 2 copies of "Surface Casing Report" on the above named well.

We are also enclosing one copy of the Well Elevation Survey on the subject named well.

Very truly yours,

CHAMPLIN OIL & REFINING CO.

Original Signed By
D. C. Carley

D. C. Carley
District Supt.

/mew

cc: Utah OGCC w/atts 2 ✓
G. A. Staples w/att
Denver office w/atts
Murphy w/atts 2
File

7

(SUBMIT IN TRIPLICATE)

Indian Agency **Navajo**

Tribal

Allottee

Lease No. **14-20-603-720**

<div style="display: flex; align-items: center;"> <div style="border: 1px solid black; padding: 5px; margin-right: 10px;"> 13 </div> <div style="border: 1px solid black; padding: 5px;"> APPROVED </div> </div>		UNITED STATES
		DEPARTMENT OF THE INTERIOR
<div style="display: flex; align-items: center;"> <div style="border: 1px solid black; padding: 5px; margin-right: 10px;"> 13 </div> <div style="border: 1px solid black; padding: 5px;"> APPROVED </div> </div>		JUL 2 1961 RICHARD B. KRAHL Mining District Engineer
GEOLOGICAL SURVEY		

R24E

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

3/20/

19 61

Navajo-111
Well No. **#3** is located **1980** ft. from **TNT** line and **660** ft. from **E** line of sec. **13**
C NE SE Sec. 13 **43S** **24E** **Salt Lake City**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Anido Creek **San Juan** **Utah**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5113.4** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned well as follows:

65 sx cement from T. D. (5454') to 5250
 40 sx cement from 3410' to 3310'
 135 sx cement from 800' to 450' (50' into surface pipe)
 15 sx cement from 30' to G. L.
 Capped well with steel post and cleaned up location.

Verbal approval for this work received from Mr. P. T. McGrath
 3/13/61.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Champlin Oil & Refining Co.

Company

Box 451

Address

Sidney, Nebraska

Original Signed By
D. C. Carley

By

District Supt.

Title

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

Tribal

Allottee _____

Lease No. 14-20-603-720

13	APPROVED	UNITED STATES
	MAR 23 1961	DEPARTMENT OF THE INTERIOR
	<i>Richard B. Krahle</i>	GEOLOGICAL SURVEY
	RICHARD B. KRAHLE	
	ACTING DISTRICT ENGINEER	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Navajo-111
#3
Well No. _____ is located _____ 1980 ft. from [N] line and _____ 660 ft. from [E] line of sec. 13
C NE SE Sec. 13 43S 24E Salt Lake City
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Mude Creek San Juan Utah
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned well as follows:

65 sz cement from T. D. (5454') to 5250

40 sz cement from 3410' to 3310'

135 sz cement from 800' to 450' (50' into surface pipe)

15 sz cement from 30' to G. L.

Capped well with steel post and cleaned up location.

Verbal approval for this work received from Mr. P. T. McGrath
3/13/61.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Champlin Oil & Refining Co.


Address Box 451

Sidney, Nebraska

Original Signed By
D. C. Carley

By _____

Title District Supt.



LOCATE WELL CORRECTLY

T43S

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

LOG OF OIL OR GAS WELL

Company Champlin Oil & Refining Co. Address Box 451, Sidney, NebraskaLessor or Tract Navajo 111 Field Anido Creek State UtahWell No. 3 Sec. 13 T. 43S R. 24E Meridian Salt Lake City County San JuanLocation 1980 ft. N. of S. Line and 660 ft. E. of E. Line of Section 8 Elevation 5113
(Derrick floor relative to sea level)

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

Original Signed By

Signed

D. C. Carley

Date 3/20/61Title District Supt.

The summary on this page is for the condition of the well at above date.

Commenced drilling 2/28/61 19 61 Finished drilling 3/14/61 19 61

OIL OR GAS SANDS OR ZONES

(Denote gas by G)

No. 1, from 5352 to 5356 No. 4, from _____ to _____

No. 2, from _____ to _____ No. 5, from _____ to _____

No. 3, from _____ to _____ No. 6, from _____ to _____

IMPORTANT WATER SANDS

No. 1, from _____ to _____ No. 3, from _____ to _____

No. 2, from _____ to _____ No. 4, from _____ to _____

CASING RECORD

Size casing	Weight per foot	Threads per inch	Make	Amount	Kind of shoe	Cut and pulled from	Perforated		Purpose
							From—	To—	
8 5/8	21.4	3 1/2	AMCA	1000	TEB	_____	_____	_____	CSG.
HISTORY OF OIL OR GAS WELL									
TO—BUREAU OF LAND MANAGEMENT, DENVER, COLORADO									

MUDDING AND CEMENTING RECORD

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
8 5/8	499.97	270 sx	Pump & Plug		

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth set _____

Adapters—Material _____ Size _____

PLUGS AND ADAPTERS

Heaving plug—Material Length Depth set

Adapters—Material Size

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out

TOOLS USED

Rotary tools were used from G. L. feet to 5443 feet, and from feet to feet

Cable tools were used from feet to feet, and from feet to feet

DATES

....., 19..... Put to producing, 19.....

The production for the first 24 hours was barrels of fluid of which% was oil;% emulsion;% water; and% sediment. Gravity, °Bé.

If gas well, cu. ft. per 24 hours Gallons gasoline per 1,000 cu. ft. of gas

Rock pressure, lbs. per sq. in.

EMPLOYEES

E. W. Early, Jr., Driller E. E. Combrink , Driller

O. T. Ash , Driller V. K. Patterson , Driller

Tool-Pusher

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
2410			Shinarump
2746			Organ Rock
3340			De Chelly
4356			Upper Hermosa
5192			Ismay A Zone
5392			Desert Creek
FROM—	TO—	TOTAL FEET	FORMATION

FORMATION RECORD—Continued

16-48004-2 U. S. GOVERNMENT PRINTING OFFICE

Casing size	Well depth	Depth	Stratigraphic per	Make	Amount	Kind of material	Cut and built from	Perforated	Purpose
	2/26/61								
No. 3' from	2/26/61								
No. 1' from									
	3/11/61								
No. 3' from									
No. 3' from									
No. 1' from	3/12/61								
Completed casing	3/23/61								
	3/23/61								

Date 3/5/1978 Title PROSPECT REPORT

so far as can be determined from all available records.

The information given hereafter is a complete and correct record of the well and all work done thereon.


Location SEC. 14 of T. 1 N. and R. 1 E. of 1 Line of 1 Range of 1 Township of 1 Elevation 1 feet

Well No. 1 Sec. 14 T. 1 N. R. 1 E. Meridian 1 County 1 State 1

Owner of Tract 1 High 1 Acres 1 State 1

Company 1 Address 1

LOCATE MEET CORRECTLY



ГОС ОЕ ОИГ ОБ САЗ МЕЛГ

GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR

UNITED STATES

1. NAME OF PERSON OR PERSONS
 2. DATE OF BIRTH
 3. DATE OF DEATH
 4. DATE OF BURIAL
 5. DATE OF CREMATION
 6. DATE OF INTERMENT
 7. DATE OF EXHUMATION
 8. DATE OF REINTERMENT
 9. DATE OF RECREMATION
 10. DATE OF REINTERMENT
 11. DATE OF RECREMATION
 12. DATE OF REINTERMENT
 13. DATE OF RECREMATION
 14. DATE OF REINTERMENT
 15. DATE OF RECREMATION
 16. DATE OF REINTERMENT
 17. DATE OF RECREMATION
 18. DATE OF REINTERMENT
 19. DATE OF RECREMATION
 20. DATE OF REINTERMENT
 21. DATE OF RECREMATION
 22. DATE OF REINTERMENT
 23. DATE OF RECREMATION
 24. DATE OF REINTERMENT
 25. DATE OF RECREMATION
 26. DATE OF REINTERMENT
 27. DATE OF RECREMATION
 28. DATE OF REINTERMENT
 29. DATE OF RECREMATION
 30. DATE OF REINTERMENT
 31. DATE OF RECREMATION
 32. DATE OF REINTERMENT
 33. DATE OF RECREMATION
 34. DATE OF REINTERMENT
 35. DATE OF RECREMATION
 36. DATE OF REINTERMENT
 37. DATE OF RECREMATION
 38. DATE OF REINTERMENT
 39. DATE OF RECREMATION
 40. DATE OF REINTERMENT
 41. DATE OF RECREMATION
 42. DATE OF REINTERMENT
 43. DATE OF RECREMATION
 44. DATE OF REINTERMENT
 45. DATE OF RECREMATION
 46. DATE OF REINTERMENT
 47. DATE OF RECREMATION
 48. DATE OF REINTERMENT
 49. DATE OF RECREMATION
 50. DATE OF REINTERMENT
 51. DATE OF RECREMATION
 52. DATE OF REINTERMENT
 53. DATE OF RECREMATION
 54. DATE OF REINTERMENT
 55. DATE OF RECREMATION
 56. DATE OF REINTERMENT
 57. DATE OF RECREMATION
 58. DATE OF REINTERMENT
 59. DATE OF RECREMATION
 60. DATE OF REINTERMENT
 61. DATE OF RECREMATION
 62. DATE OF REINTERMENT
 63. DATE OF RECREMATION
 64. DATE OF REINTERMENT
 65. DATE OF RECREMATION
 66. DATE OF REINTERMENT
 67. DATE OF RECREMATION
 68. DATE OF REINTERMENT
 69. DATE OF RECREMATION
 70. DATE OF REINTERMENT
 71. DATE OF RECREMATION
 72. DATE OF REINTERMENT
 73. DATE OF RECREMATION
 74. DATE OF REINTERMENT
 75. DATE OF RECREMATION
 76. DATE OF REINTERMENT
 77. DATE OF RECREMATION
 78. DATE OF REINTERMENT
 79. DATE OF RECREMATION
 80. DATE OF REINTERMENT
 81. DATE OF RECREMATION
 82. DATE OF REINTERMENT
 83. DATE OF RECREMATION
 84. DATE OF REINTERMENT
 85. DATE OF RECREMATION
 86. DATE OF REINTERMENT
 87. DATE OF RECREMATION
 88. DATE OF REINTERMENT
 89. DATE OF RECREMATION
 90. DATE OF REINTERMENT
 91. DATE OF RECREMATION
 92. DATE OF REINTERMENT
 93. DATE OF RECREMATION
 94. DATE OF REINTERMENT
 95. DATE OF RECREMATION
 96. DATE OF REINTERMENT
 97. DATE OF RECREMATION
 98. DATE OF REINTERMENT
 99. DATE OF RECREMATION
 100. DATE OF REINTERMENT

March 22, 1961

United States Dept. of the Interior
Geological Survey
P. O. Box 959
Farmington, New Mexico

Re: Navajo-111 No. 3
San Juan County, Utah

Gentlemen:

Please find enclosed the following papers in regard to the
above named well:

- A. Log of Well (Original and 2 copies)
- B. Sonic Log 2 copies
- C. Induction-Electrical Log 2 copies

Very truly yours,

CHAMPLIN OIL & REFINING CO.

Original Signed By
D. C. Carley

D. C. Carley
District Supt.

/new

Encls.

cc: OGCC Utah 1 copy of each encls. 2 - Log of Well
G. A. Staples
Murphy
File

Champlin Oil & Refining Co.

P. O. BOX 451
SIDNEY, NEBRASKA

April 13, 1961

Utah Oil & Gas Commission
State Capitol Building
Salt Lake City 14, Utah

Re: Report of Operations and
Well Status Report

Gentlemen:

Attached hereto is an original and one copy of subject named
report covering our production for March, 1961.

Very truly yours,

CHAMPLIN OIL & REFINING CO.

D. C. Carley
D. C. Carley
District Supt.

/mew

Atts.

STATE OF UTAH
OIL & GAS CONSERVATION COMMISSION

Salt Lake City 14, Utah

REPORT OF OPERATIONS AND WELL STATUS REPORT

State Utah County San Juan Field or Lease Unnamed

The following is a correct report of operations and production (including drilling and producing wells) for

March 61
....., 19.....Agent's address Box 451Company Champlin Oil & Refining Co.Sidney, NebraskaSigned *W. L. Karley*Phone 4551Agent's title District Supt.14-20-603-720State Lease No. Federal Lease No. Indian Lease No. Fee & Pat. ☐

Sec. & ¼ of ¼	Twp.	Range	Well No.	*Status	Oil Bbls.	Water Bbls.	Gas MCF's	REMARKS (If drilling, Depth; if shut down, Cause; Date & Results of Water Shut-Off Test; Contents of Gas; and Gas-Oil Ratio Test)
NE SE 13	43S	24E	*3	Dry Hole				
* Drilled to 5305'. Cored from 5305-65'. DST 5310-65, 5/8 x 1" chokes. ISI 30, opened 1 hour, FSI 30 minutes. Fair blow. No gas to surface. Recovered 115' oil-gas cut-mud, 450' gas cut salt water. BHP's 70-265. Drilled to total depth of 5454'. Ran logs.								
Plugged well as follows:								
65 sx cement from T. D. 5454' to 5250'								
40 sx cement from 3410' to 3310'								
135 sx cement from 800' to 450' (50' into surface pipe)								
15 sx cement from 30' to G. L.								
Capped well with steel post and cleaned up location.								

NOTE: Report on this form as provided
for in Rule C-22. (See back of form.)

FILE IN DUPLICATE

*STATUS: F-Flowing P-Pumping GL-Gas Lift
SI-Shut In D-Dead
GI-Gas Injection TA-Temp. Aban.
WI-Water Injection

Champlin Oil & Refining Co.

P. O. BOX 431
SIDNEY, NEBRASKA

March 23, 1962

Utah Oil & Gas Conservation Commission
310 Newhouse Building
10 Exchange Place
Salt Lake City 11, Utah

Gentlemen:

Enclosed please find two approved copies of U.S.G.S. Form
9-331b "Subsequent Report of Abandonment" on our Navajo III
Well No. 3 located in San Juan County, Utah.

Very truly yours,

CHAMPLIN OIL & REFINING CO.

D. C. Carley

D. C. Carley
District Superintendent

/mew

cc: Murphy Corp.
G. A. Staples
Denver office
File

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo
Tribal

	13	

UNITED STATES
APPROVED
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allotype 14-20-603-720
Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

1-3-_____, 1962

Navajo-111
Well No. 3 is located 1980 ft. from N line and 660 ft. from E line of sec. 13
C-NE-SE Sec. 13 43S 24E Salt Lake City
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Anido Creek San Juan Utah
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5113.4 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned well as follows:

1. Placed 65 sack cement plug from T. D. (5454') to 5250'.
2. Placed 40 sack cement plug from 3410' to 3310'.
3. Placed 135 sack cement plug from 800' to 450'.
4. Placed 15 sack cement plug from 30' to 1 1/2' below ground level.
5. Installed steel marker, cleaned location, and closed pits.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Champlin Oil & Refining Co.
Address Box 451
Sidney, Nebraska

Original Signed by
J. H. Rankin
By _____
Title District Engineer